



Photo 1 – Main wreckage site.



Photo 2 – Fragmented left wing in debris path.



Photo 3 – Airplane’s engine at main wreckage site.



Photo 4 – Airplane’s Propeller at Main Wreckage Site.